

Appendix D - OMA Lead-Based Paint Survey
Master Building List - 15 Sep 2005

Received a Lead Survey					
Needs a Lead Survey					
Low Priority for Survey					
BUILDING NUMBER	STATE	SQUARE FOOTAGE	YEAR BUILT	REMARKS	SURVEYED BY
1		33	2001		
5		33	2002		
6		33	2002		
7		33	2001		
8		33	2001		
10		33	2001		
11		33	2001		
12		33	2001		
27		750	1985		
32	T	2720	1950		BAT 2001
38	T	16038	1967		BAT 2002
39	T	14523	1942		BAT 2003
42		1500	1950		
43	T	7780	1983		
44		750	1962		
51		750	1992		
52		750	1992		
53		750	1991		
54		750	1991		
55		750	1992		
80	K	28580	1991		
82	K	4500	1997		
83	K	67500	1997		
88		8240	1999		
89	T	11545	1975		BAT 2003
91	K	12873	1972		BAT 2003
92	K	3074	1960	Gas Station	BAT 2003
93	T	17492	1949		BAT 2003
94	K	3430	1958		BAT 2003
95	K	21864	1954		
96	T	6059	1957		BAT 2003
97	K	3250	1958		Advent 1995
98	K	102645	1958		Advent 1995
99	K	4988	1958		Advent 1995
100	K	800	1985		
123	K	18864	1943		
125	K	18864	1943		
127	K	783	1991		
201	K	3843	2001		
202	K	124712	1997		
230	T	8042	1942	Demo List '03	BAT 2005
232	T	8042	1942	Demo List '03	
234	T	8042	1942	Demo List '03	
602	T	3108	1943		BAT 2002
603	T	3108	1943		
604	T	3171	1943		BAT 2002
605	T	3171	1943		BAT 2002
606	T	3972	1943		
615	T	1920	1942	Car Wash	BAT 2003
650	T	455469	1982		
719	T	1550	1942		BAT 2002
723	T	5310	1942		BAT 2002
731	T	4320	1942		BAT 2002
734	T	5310	1942	Demo List '03	
737	T	1672	1943	Demo List '99	
744	T	9000	1982		
749	T	3108	1943		BAT 2001
750	T	3108	1943		BAT 2001

Appendix D - OMA Lead-Based Paint Survey

Master Building List - 15 Sep 2005

Received a Lead Survey					
Needs a Lead Survey					
Low Priority for Survey					
751	T	18240	1943		BAT 2001
752	T	18299	1943		BAT 2001
753	T	19249	1943		BAT 2001
754	T	18299	1943		BAT 2001
755	T	18299	1943		BAT 2001
756	T	18299	1943		BAT 2001
757	T	3108	1943		BAT 2001
760	T	1350	1942	Can not Locate	
762	T	9000	1984		
763	T	3055	1997		
826	T	9000	1942		
832	T	13048	1942	Demo List '03	
840	T	9000	1942		BAT 2001
842	T	9000	1942		BAT 2003
843	T	9000	1942	Demo List '03	
844	T	9000	1942		BAT 2001
845	T	9000	1942	Demo List '03	
846	T	9000	1942		BAT 2001
847	T	10655	1942	Demo List '03	
849	T	10050	1942	Demo List '03	
850	T	10452	1942		Advent 1996
853	T	9000	1942		BAT 2003
854	T	5411	1967		BAT 2002
855	T	9000	1967		BAT 2003
857	T	9000	1942		BAT 2003
858	T	3808	1942		BAT 2002
860	T	55558	1942		BAT 2003
862	T	9000	1942		BAT 2002
863	T	11039	1942		BAT 2002
864	T	300	1970		BAT 2002
865	T	10691	1942		
867	T	10668	1942		BAT 2004
868	T	13104	1942		BAT 2002
869	T	3076	1942		BAT 2002
871	T	6901	1942		BAT 2002
873	T	6808	1942		BAT 2002
875	T	4061	1942		BAT 2002
877	T	3578	1949		BAT 2004
886	T	240	1957	Not a Bldg.	
888	T	1920	1984		
889	T	1920	1984		
890	T	4480	1984		
892	T	12078	1986		
893	T	4000	1986		
901	T		1979		
902	T	103928	1985		
905	T	1200	1986		
907	T	9000	1942		BAT 2003
908	T	9000	1942		BAT 2002
909	T	9000	1942	Storage Bldg.	
1043	T	312	1959	Not a Bldg.	
1230	T	312	1960	Not a Bldg.	
1230	T	312	1960		BAT 2005
1501	T	32643	1963		BAT 2003
1565	T	340	1957	Pump House	BAT 2005
1567	T	1936	1958		BAT 2003
1568	T	1632	1964	Warehouse	BAT 2005
1569	T	2800	1985		
1572	T	1440	1980		
1581	T	3484	1975		BAT 2003
1582	T	8996	1975		BAT 2003

Appendix D - OMA Lead-Based Paint Survey

Master Building List - 15 Sep 2005

Received a Lead Survey					
Needs a Lead Survey					
Low Priority for Survey					
1583	T	9914	1975		BAT 2003
1583	T		1975	Generator	
1584	T	9195	1975		BAT 2003
1585	T	6228	1975		BAT 2003
1585	T		1975	Generator	
1595	T	1179	1983		
1602	T	16	1963	Not a Bldg.	
1603	T	2100	1975	Warehouse	BAT 2005
1604	T	126	1970	Not a Bldg.	
1608	T	168	1990		
1746	T		1942		Advent 1996
2104	T	2000	1942	Demo List '03	BAT 2005
2107	T	7528	1942	Demo List '03	
2110	T	2000	1942		BAT 2003
2112	T	3500	1967		BAT 2003
2114	T	3500	1967		BAT 2003
2115	T	82625	1997		
2129	T	2800	1977		Advent 1996
2133	T	5310	1942		BAT 2003
2159	T	2570	1943		BAT 2002
2170	T	5310	1942	Demo List '03	BAT 2005
2172	T	5310	1942	Demo List '03	BAT 2005
2174	T	5310	1942	Demo List '03	
2176	T	5310	1942	Demo List '03	
2178	T	5310	1942	Demo List '03	
2180	T	5310	1942		BAT 2003
2182	T	5310	1942		
2186	T	5310	1942		BAT 2003
2188	T	5310	1942	Demo List '03	
2191	T	9352	1948		BAT 2002
2192	T	1877	1952		BAT 2003
2193	T	950	1952		BAT 2003
2203	T	1750	1943		BAT 2002
2204	T	2260	1942		BAT 2002
2205	T	1263	1942	Demo List '03	BAT 2005
2206	T	1250	1942		BAT 2002
2207	T	3500	1942	Demo List '03	
2208	T	1250	1942		BAT 2002
2209	T	2750	1942		BAT 2002
2250	T	2500	1943		BAT 2002
2251	T	2625	1943		BAT 2002
2253	T	2338	1942		BAT 2002
2255	T	5310	1942		BAT 2002
2257	T	5310	1942		BAT 2002
2259	T	3075	1943		BAT 2002
2261	T	4000	1993		
2267	T	2995	1943		BAT 2002
2269	T	2427	1942		BAT 2002
2270	T	18124	1949		Advent 1997
2301	T	3663	1942		BAT 2002
2303	T	3746	1942		BAT 2002
2304	T	3500	1967		BAT 2002
2310	T	5310	1942		BAT 2002
2312	T	5310	1942		BAT 2002
2314	T	5310	1942		BAT 2002
2316	T	5310	1942		BAT 2002
2318	T	5310	1942		BAT 2002
2320	T	5310	1942		BAT 2002
2322	T	5310	1942		BAT 2002
2324	T	5310	1942		BAT 2002
2325	T	2625	1943	Demo List '01	

Appendix D - OMA Lead-Based Paint Survey

Master Building List - 15 Sep 2005

Received a Lead Survey					
Needs a Lead Survey					
Low Priority for Survey					
2326	T	5310	1942		BAT 2002
2330	T	5310	1942		BAT 2002
2332	T	5310	1942		BAT 2002
2334	T	5310	1942	Demo List '03	
2401	T	1250	1942		BAT 2002
2402	T	3500	1942		BAT 2002
2403	T	2160	1943	Demo List '99	
2404	T	169	1987		
2427	T	5310	1942		BAT 2002
2429	T	5310	1942	Demo List '03	
2430	T	2503	1943		BAT 2002
2431	T	2560	1943		BAT 2002
2432	T	2250	1942	Demo List '03	BAT 2005
2435	T	3500	1967		BAT 2002
2436	T	1200	1943		BAT 2002
2437	T	4800	1994		
2438	T	2503	1943	Demo List '03	BAT 2002
2439	T	4800	1994		
2441	T	4800	1994		
2446	T	2500	1943	Demo List '02	BAT 2002
2448	T	2250	1942	Demo List '02	BAT 2002
2506	T	6490	1943		BAT 2002
2515	T	5310	1942		BAT 2002
2517	T	5310	1942		BAT 2002
2519	T	5310	1942		BAT 2002
2525	T	4800	1994		
2530	T	2500	1943		BAT 2002
2531	T	2500	1943		BAT 2004
2532	T	2250	1942		BAT 2002
2533	T	2287	1942		BAT 2002
2534	T	2248	1942		
2535	T	1845	1943		BAT 2002
2536	T	2573	1943		BAT 2002
2537	T	2573	1943		BAT 2002
2538	T	2500	1943		BAT 2002
2539	T	2500	1943	Demo List '99	
2541	T	1850	1943		BAT 2003
2546	T	2500	1943		BAT 2002
2554	T	5310	1942		BAT 2002
2556	T	5400	1942	Demo List	
2570	T	1364	1942		BAT 2003
2572	T	2016	1954		BAT 2003
2573	T	2016	1954		BAT 2003
2575	T	8667	1954		BAT 2002
2577	T	42470	1965		Advent 1996
2601	T	31386	1971		BAT 2002
2603	T	23493	1942	Demo List '03	
2604	T	22810	1942		BAT 2002
2605	T	4070	1942	Demo List '03	
2607	T	3721	1942		BAT 2003
2613	T	4320	1942	Demo List '03	
2615	T	2988	1943		BAT 2003
2617	T	2500	1943	Demo List '96	
2625	T	2938	1942	Demo List '03	
2627	T	3150	1942	Demo List '03	
2638	T	5310	1942	Demo List '03	
2640	T	5310	1942	Demo List '03	
2642	T	5310	1942	Demo List '97	
2646	T	5310	1942	Demo List '03	BAT 2003
2647			1983	Car Port	
2648	T	5412	1942	Demo List '03	BAT 2003

Appendix D - OMA Lead-Based Paint Survey
Master Building List - 15 Sep 2005

Received a Lead Survey					
Needs a Lead Survey					
Low Priority for Survey					
2660	T	4000	1993		
2699	T	3319	1972		BAT 2003
2702	K	104978	1976		BAT 2003
2703	K	6011	1986		
2715	K	5310	1942	Demo List '03	BAT 2002
2719	K	5310	1942	Demo List '03	BAT 2002
2721	K	5310	1942	Demo List '03	BAT 2002
2723	K	5310	1942	Demo List '03	BAT 2002
2725	K	5310	1942	Demo List '03	BAT 2002
2727	K	5310	1942	Demo List '03	BAT 2002
2737	K	2500	1942	Demo List '03	
2739	K	2750	1942	Demo List '03	BAT 2003
2744	K	5310	1942	Demo List '03	BAT 2002
2745	K	13249	1983		
2746	K	3000	1942		BAT 2002
2762	K	1200	1989		
2840	K	110177	1993		
2842	K	42822	1967		Advent 1996
2902	K	7531	1942		BAT 2003
2904	K	2750	1942		BAT 2004
2905	K	2000	1942		BAT 2005
2906		3000	1993		
2907	K	4800	1942		BAT 2003
2912	K	4170	1967		BAT 2003
2931	K	5310	1942		BAT 2003
2932	K	2950	1942		BAT 2002
2933	K	5310	1942		BAT 2003
2934	K	2950	1942		BAT 2002
2935	K	5310	1942		BAT 2003
2936	K	3250	1942		BAT 2003
2937	K	5310	1942		BAT 2003
2938	K	3250	1942		BAT 2003
2939	K	3250	1942		BAT 2003
2941	K	2950	1942		BAT 2003
2950	K	3783	1942		BAT 2002
2951	K	2500	1942		BAT 2002
2994	K	12551	1954		
2995	K	12551	1954		BAT 2004
2996	K	12551	1954		BAT 2004
2997	K	12551	1954		BAT 2002
3000	K	5952	1976		BAT 2003
3068	K	5000	1988		
3069	K	23765	1993		
3071	K	23765	1993		
3101	K	3746	1942		BAT 2003
3102	K	1750	1942		BAT 2003
3103	K	1295	1942		BAT 2002
3107	K	2250	1942		BAT 2002
3109	K	4828	1942		BAT 2003
3110	K	1250	1942		
3112	K	3500	1967		BAT 2002
3202	K	13381	1942		BAT 2002
3204	K	2250	1942		BAT 2003
3206	K	3746	1942		BAT 2002
3207	K	2581	1956		BAT 2003
3208	K	3598	1958		BAT 2003
3209	K	3598	1958		BAT 2003
3210	K	2581	1956		BAT 2003
3211	K	39722	1952		BAT 2003
3212	K	39722	1952		BAT 2002
3213	K	42627	1952		BAT 2002

Appendix D - OMA Lead-Based Paint Survey

Master Building List - 15 Sep 2005

Received a Lead Survey					
Needs a Lead Survey					
Low Priority for Survey					
3214	K	42627	1952		BAT 2003
3215	K	39809	1952		BAT 2002
3216	K	39809	1952		BAT 2003
3217	K	39722	1952		BAT 2003
3218	K	39722	1952		Advent 1996
3303	K	995	1992		
3304	K	3500	1967		BAT 2003
3305	K	3500	1967		BAT 2003
3306	K	4200	1942		BAT 2003
3307	K	2816	1942		BAT 2002
3308	K	2252	1942		BAT 2002
3411	K	20918	1966		BAT 2003
3601	K	7535	1942		BAT 2002
3603	K	14606	1979		
3610	K	20618	1978		Advent 1997
3672	K	25241	1986		
3680	K	15228	1983		
3686	K	15228	1983		
3706	K	4000	1984		
3707	K	1035	1984		
3713	K	44156	1982		BAT 2005
3717	K	13895	1982		
3721	K	6673	1983		
3725	K	44156	1982		BAT 2005
3730	K	33104	1983		BAT 2005
3731	K	33275	1982		BAT 2005
3748	K	33104	1977		BAT 2002
3750	K	33104	1978		BAT 2002
3754	K	33284	1978		BAT 2005
3755	K	15228	1983		
3759	K	15228	1983		
3763	K	11856	1977		
3765	K	15228	1983		
3766	K	44106	1977		BAT 2002
3767	K	20234	1977		
3780	K	9855	1979		
3902	K	13045	1977	Steam Plant	
3910	K	16264	1984		
3931	K	369	1983		
3932	K	20618	1978		Advent 1997
3933	K		1992		
3934	K	11200	1991		
3958	K	5786	1977		
3962	K	9855	1979		
3968	K	3560	1977		BAT 2003
4013	K	15228	1977		
4017	K	15228	1977		BAT 2003
4021	K	11856	1977		
4024	K	33104	1977		BAT 2005
4025	K	12375	1977		
4028	K	33104	1977		BAT 2005
4029	K	20234	1977		BAT 2003
4033	K	33104	1977		BAT 2005
4038	K	44156	1977		BAT 2005
4039	K	33104	1977		BAT 2005
4044	K	33104	1977		BAT 2005
4053	K	22053	1977		BAT 2002
4054	K	25241	1977		BAT 2003
4057	K	33104	1977		BAT 2003
4061	K	16150	1977		Advent 1998
4062	K	15228	1977		

Appendix D - OMA Lead-Based Paint Survey

Master Building List - 15 Sep 2005

Received a Lead Survey					
Needs a Lead Survey					
Low Priority for Survey					
4067	K	44106	1977		BAT 2005
4068	K	15228	1977		BAT 2003
4190	K	6153	1985		
4199	K	9520	1960		BAT 2002
4301	K	3414	1976		
4858	K	2519	1958		
4859	K	1513	1975		BAT 2002
4860	K	1513	1975		BAT 2002
5005		40	1994		
5115	T	2945	1943		BAT 2002
5117	T	2945	1943		BAT 2002
5121	T	1800	1990		
5123	T	8208	1943		BAT 2002
5124	T	9000	1984		
5125	T	8208	1943		BAT 2002
5128	T	2921	1986		
5129	T	800	1989		
5130	T	1999	1997		
5131	T	1945	1997		
5132	T	96	1996		
5133	T	7000	1998		
5134		7000	1999		
5135		7000	2001		
5160	T	2924	1987		
5161	T	2464	1989		
5201	T	10400	1963		BAT 2003
5202	T	29300	1964		BAT 2003
5207	T	169375	1954	Warehouse	BAT 2005
5209	T	4840	1998		
5210	T	86708	1954	Warehouse	
5211	T	185	1969		
5212	T	2160	1989		
5213	T	10000	1967	Warehouse	
5214	T	25920	1968	Warehouse	
5216	T	30000	1991		
5217	T	1020	1990		
5220	T	3200	2001		
5221	T	5250	1996		
5222	T	7500	1999		
5223	T	9000	1984		
5224	T	5105	1997		
5225	T	3200	1990		
5226	T	5106	1997		
5287		600	1995		
5289	T	4800	1995		
5290	T	2290	1981		
5291	T	1161	1986		
5326	T	3156	1943	Demo List '02	BAT 2002
5328	T	1350	1942		BAT 2002
5330	T	1000	1943		BAT 2002
5333	T	1350	1942		BAT 2005
5346	T	2732	1943		BAT 2003
5348	T	2732	1943		BAT 2003
5380	T	26460	1989		
5436		14960	1942		
5437	T	1600	2001		
5438	T	5250	2000		
5441			1991		
5504	T	4046	1994		
5505	T	99270	1994		
5506	T	120	1994		

Appendix D - OMA Lead-Based Paint Survey
Master Building List - 15 Sep 2005

Received a Lead Survey					
Needs a Lead Survey					
Low Priority for Survey					
5507	T	120	1994		
5509	T	494	1994		
5511	T	9576	1943		
5513	T	10241	1943		BAT 2002
5514	T	995	1992		
5551	T	2393	1963		BAT 2003
5552	T	273	1963		BAT 2003
5580	T	14606	1977		BAT 2003
5611	T	9770	1943		BAT 2002
5613	T	10496	1943		BAT 2004
5640	T	7036	1997		
5641	T	7036	1997		
5646	T	7036	1997		
5658	T	17630	1986		
5661	T	22480	1970		
5663	T	12204	1962		
5665	T	800	1982		
5667	T	3200	1999		
5668	T	8064	1975		
5670	T	8064	1972		
5702	T	14000	1968		BAT 2003
5705	T	7519	2001		
5710	T	2200	1985		
5733	T	7700	1985	Demo List '03	
5740	T	14173	1959		BAT 2003
5848	K	1350	1942		BAT 2003
5855			1942	Grease Rack	
5860	K	5000	1994		
5875		1248	1970		BAT 2003
5908	K	2675	1942		BAT 2002
5916	K	3376	1942		BAT 2003
5917			1942	Grease Rack	
5918	K	2732	1942		BAT 2002
5920	K	2732	1942		BAT 2003
5926	K	2500	1994		
5955			1942		
5962	K	4000	1983		
5978	K	761	2000		
5979	K	74360	2000		
5980	K	12133	1963		
6001	T	693	1989		
6001		693	1989		
6002	T	400	1989		
6078	T	1800	1998		
6080	T	7650	1968		BAT 2003
6080		1160	1986		
6080		1160	1986		
6080		5000	1989		
6081	T	4853	1945		BAT 2002
6082	T	1139	1986		
6085	T	1139	1986		
6087	T	10816	1977		BAT 2003
6087		405	1977		BAT 2004
6087		2400	1985		
6088	T	4988	1980		
6090		196	1996		
6090		2400	1996		
6090		5000	1996		
6090			1994		BAT 2002
6091	T	324	1969		BAT 2002
6091	T	324	1969		BAT 2002

Appendix D - OMA Lead-Based Paint Survey

Master Building List - 15 Sep 2005

Received a Lead Survey					
Needs a Lead Survey					
Low Priority for Survey					
6092	K	693	1989	Demo List '95	
6093	T	2064	1996		
6095	K	880	1989		
6096	K	5120	1968	Warehouse	BAT 2003
6097	K	5120	1968	Warehouse	BAT 2003
6098	K	5120	1968	Warehouse	BAT 2003
6099		3200	1987	Warehouse	
6110	K	7037	1996		
6113	K	7037	1997		
6118	K	7037	1996		
6129	K	7036	1996		
6139	K	2686	1958		BAT 2003
6140	K	3867	1958		BAT 2003
6142	K	2339	1960		BAT 2003
6143	K	64	1960		BAT 2003
6144					BAT 2003
6145	K	23450	1974		BAT 2003
6146	K	4800	1999		
6203	K	151	1958		BAT 2003
6205	K		1958	Grease Rack	
6222	K	8208	1942		BAT 2003
6225	K	60174	1990		
6226	K	120	1990		
6234	K	7970	1990		
6240	K	5451	1991		
6241	K	6851	1991		
6247	K	17190	1991		
6248	K	9598	1991		
6249	K	120	1991		
6254	K	9338	1954		Advent 1997
6256	K	5284	1954	Motor Pool	BAT 2003
6257	K	4808	1954	Motor Pool	BAT 2003
6258	K	12438	1971	Motor Pool	BAT 2003
6266	K	192	1958		BAT 2005
6268	K	151	1958	Motor Pool	
6302	K	5615	1978		BAT 2005
6303	K	124	1958	Motor Pool	BAT 2003
6304	K	5385	1978		BAT 2004
6306	K	5615	1978		
6308	K	5385	1978		
6310	K	7037	1997		
6311			1978		
6312	K	6182	1978		BAT 2005
6314	K	6182	1978		BAT 2005
6316	K	6182	1978		BAT 2004
6318	K	6182	1978		BAT 2005
6327	K	192	1978		BAT 2005
6329	K	192	1978		
6390	K	12792	1985		
6391	K	3106	1994		
6419	K	7037	1997		
6421	K	6898	1997		
6426	K	10944	1942		
6446	K	9576	1942		
6448	K	9576	1942		
6454	K	10000	1963		BAT 2002
6456	K	10000	1942		BAT 2002
6460	K	10000	1963		BAT 2002
6464	K	10000	1963		BAT 2002
6468	K	10000	1963		BAT 2003
6470	K	10000	1963		BAT 2002

Appendix D - OMA Lead-Based Paint Survey

Master Building List - 15 Sep 2005

Received a Lead Survey					
Needs a Lead Survey					
Low Priority for Survey					
6474	K	10000	1963		BAT 2003
6486	K	2000	1994		BAT 2002
6488	K	21623	1994		BAT 2002
6489	K	9052	1994		BAT 2002
6490	K	600	1985		
6492	K	7037	1998		
6494	K	7037	1998		
6498	K	3750	1993		
6502	K	5615	1978		
6504	K	5385	1978		
6506	K	5615	1978		
6508	K	5385	1978		
6511	K		1978		BAT 2005
6512	K	6182	1978		BAT 2005
6514	K	6182	1978		BAT 2005
6516	K	6182	1978		BAT 2005
6518	K	6182	1978		BAT 2005
6523	K		1978		
6525			2003		
6527	K	192	1978		
6529	K	192	1978		
6530	K	2558	1986		
6531	K	460	1985		
6532	K	231	1986		
6533	K	2688	1985		
6535	K	21745	1985		
6536	K	84	1985		
6538	K	713	1985		
6548	K	10944	1990		
6551	K	16758	1981		
6555	K	18377	1984		
6559	K	31415	1985		
6563	K	19121	1987		
6565	K	305	1997		
6601	T	4320	1959	Barn	
6602	T	4356	1959	Barn	BAT 2004
6604	T	2000	1964	Bunker	BAT 2005
6605	T	2000	1964	Bunker	
6606	T	2000	1964	Bunker	BAT 2005
6607	T	2000	1964	Bunker	
6608	T	2000	1964	Bunker	BAT 2005
6609	T	2000	1964	Bunker	
6610	T	2000	1964	Bunker	
6611	T	2000	1964	Bunker	
6612	T		1943	Pumping Station	BAT 2004
6613	T	3456	1990		
6614	T	1260	1973		
6615	T	800	1943		BAT 2002
6617	T	10800	1973		
6618	T	4752	1991		
6619	T	6000	1975	Barn	BAT 2005
6619		120	1983		BAT 2005
6620	T	515	1978		BAT 2002
6621	T	1706	1981		
6621		1706	1981		
6621		3200	1985		
6622	T	153	1976		
6623	T		1976		BAT 2005
6623	T		1976	Storage Tank	BAT 2005
6624	T	261	1976		BAT 2005
6625	T	3565	1981		

Appendix D - OMA Lead-Based Paint Survey

Master Building List - 15 Sep 2005

Received a Lead Survey					
Needs a Lead Survey					
Low Priority for Survey					
6626	T	3565	1981		
6627	T	30235	1991		
6628		157	1976		
6628	T	5200	1987		
6628		5200	1987		
6629	T	4800	1989		
6631		320	2000		
6631		180	2000		
6633	T	16062	1994		
6634	T	3546	1976		BAT 2003
6635	T	4000	1989		
6636	T	63721	1987		
6636		249	1987		
6636		249	1987		
6637	T	4800	1989		
6639	T	7487	1996	Air Field Tower	
6643	T	96	1976	Pump house	BAT 2005
6645	T	2944	1983		
6645		276	1983		
6646	T	1560	1984		
6647	T	1701	1984		
6647		1920	1984		
6647		1400	1984		
6647		1520	1984		
6647		2760	1984		
6647		828	1984		
6647		828	1984		
6647		978	1984		
6647		978	1984		
6647		978	1984		
6647		978	1984		
6647		978	1984		
6647		978	1984		
6647		1944	1993		
6647		1944	1993		
6647		1944	1993		
6647		1750	1993		
6648	T	10430	1999		
6657	T	820	1973	Cabin	BAT 2003
6660	T	733	1994		BAT 2002
6691	T	36	1952	Not a Bldg.	
6693	T	100	1955	Fire Tower	BAT 2004
6694	T	100	1955	Fire Tower	BAT 2004
6694	T	100	1955	Not a Bldg.	BAT 2004
6695	T	600	1998		
6708	T	2581	1965		BAT 2002
6709	T	38145	1954		BAT 2003
6710	T	38406	1954		BAT 2002
6711	T	38329	1954		BAT 2002
6712	T	38285	1954		BAT 2002
6713	T	3610	1958		BAT 2002
6714	T	2686	1958	Demo List	
6715	T	18902	1954		BAT 2002
6717	T	2581	1955		BAT 2002
6718	T	31869	1954		BAT 2002
6719	T	31779	1954		BAT 2002
6721	T	7714	1958	Chapel	BAT 2003
6722	T	3867	1958		BAT 2002
6723	T	3610	1958		BAT 2002
6725	T	38241	1954		

Appendix D - OMA Lead-Based Paint Survey
Master Building List - 15 Sep 2005

Received a Lead Survey					
Needs a Lead Survey					
Low Priority for Survey					
6726	T	38160	1954		
6727	T	38312	1954		BAT 2002
6729	T	3610	1958		BAT 2002
6730	T	38138	1954		BAT 2002
6731	T	43509	1954		BAT 2002
6732	T	38442	1954		BAT 2002
6733	T	37977	1954		BAT 2002
6734	T	3610	1958		BAT 2002
6735	T	2746	1955		BAT 2002
6736	T	2581	1965		BAT 2002
6740	T	4141	1982		
6744	T	7200	1989		
6759	T	6198	2001		
6760	T	15142	2001		
6761	T	20494	2001		
6762	T	93516	2001		
6763	T	125066	2000		
6764	T	125066	2000		
6765	T	14284	1999		
6766	T	38647	1999		
6767	T	14284	1999		
6768	T	38647	2001		
6769	T	17144	2001		
6770	T	38647	2001		
6801	T	32652	1954		BAT 2003
6802	T	120	1991		
6803	T	100	1955		BAT 2003
6804	T	5217	1954	Motor Pool	
6806	T		1958	Not a Bldg.	
6808	T	4752	1963	Motor Pool	
6809	T	151	1958	Motor Pool	
6810	T	124	1958	Motor Pool	
6811	T	151	1958	Motor Pool	
6812	T	192	1958	Motor Pool	BAT 2004
6817	T	151	1958	Motor Pool	BAT 2005
6818	T	124	1958	Motor Pool	
6819	T	151	1958	Motor Pool	BAT 2005
6821	T	192	1954	Motor Pool	
6823	K		1958		BAT 2005
6827	T	120	1997		
6828	T	34155	1997		
6829	T	6300	1997		
6830	T	120	2000		
6832	T	7000	2000		
6833	T	12975	2000		
6835	T	120	2000		
6836	T	12506	2000		
6837	T	6300	2000		
6838	T	21417	2000		
6843	T	5284	1954	Motor Pool	BAT 2004
6844	T	4748	1954	Motor Pool	BAT 2005
6846	T	192	1954	Motor Pool	BAT 2005
6847	T	5105	1954	Motor Pool	BAT 2005
6849	T	5217	1954	Motor Pool	BAT 2005
6850	T	4748	1954	Motor Pool	BAT 2003
6870	T		1987		
6874	T	29017	1987		
6879	T	8698	1999		
6880	T	1764	1987	Grease Rack	
6881	T	120	1987		
6883	T	21980	1999		

Appendix D - OMA Lead-Based Paint Survey
Master Building List - 15 Sep 2005

Received a Lead Survey					
Needs a Lead Survey					
Low Priority for Survey					
6884	T	1040	1987		
6886	T	5600	1987		
6887	T	10248	1987		
6888	T	3500	1994		
6889	T	199	1994		
6890	T	29792	1994		
6891	T	120	1994		
6892	T	30130	1994		
6893	T	120	1994		
6894	T	7000	2002		
6898	T	400	1999		
6899	T	800	1999		
6885	T		1996	Air Assault Tower	BAT 2003
6885B	T		1996	Ramp #1	BAT 2003
6885C	T		1996	Ramp #2	BAT 2003
6885D	T		1996	Ramp #3	BAT 2003
6885E	T		1996	Ramp #4	BAT 2003
6901	T	9303	1954		BAT 2002
6902	T	3867	1958		BAT 2003
6903	T	2686	1958		BAT 2003
6904	T	2581	1965		BAT 2003
6905	T	2581	1965		BAT 2003
6906	T	2581	1965		BAT 2003
6907	K	2581	1965		BAT 2003
6908	K	2581	1965		BAT 2003
6909	T	31758	1954		BAT 2004
6910	T	38089	1954		BAT 2004
6911	T	38280	1954		BAT 2004
6912	T	38310	1954		BAT 2005
6913	T		1958		BAT 2003
6914	T	3610	1958		BAT 2003
6915	T	3610	1958		BAT 2002
6916	T	2581	1958		BAT 2002
6917	T	38480	1956		BAT 2002
6918	T	38646	1956		BAT 2002
6919	K	38711	1956		BAT 2001
6920	K	38649	1956		BAT 2001
6921	K	38512	1956		Bate 2000
6921		1470	1976		BAT 2003
6922	K	38691	1956		BAT 2003
6923	K	38465	1956		BAT 2003
6924	K	2581	1963		BAT 2003
6924A		3688	1978		BAT 2005
6925	K	3610	1958		BAT 2003
6926	K	2581	1956		BAT 2003
6927	K	38118	1954		BAT 2005
6928	K	38120	1954		BAT 2005
6929	K	38281	1954		BAT 2005
6930	K	38196	1954		BAT 2005
6931	K	31713	1954		BAT 2005
6932	K	2581	1956		BAT 2003
6933	K	3610	1958		BAT 2003
6934	K	3610	1958		BAT 2003
6935	K	2581	1956		BAT 2003
6936	K	31735	1954		BAT 2005
6937	K	37900	1954		BAT 2005
6938	K	38039	1954		BAT 2005
6939	K	38137	1954		Advent 1999
6940	K	38127	1954		BAT 2002
6942	K	38098	1954		BAT 2005
6943	K	38049	1954		BAT 2003

Appendix D - OMA Lead-Based Paint Survey
Master Building List - 15 Sep 2005

Received a Lead Survey					
Needs a Lead Survey					
Low Priority for Survey					
6944	K	38063	1954		BAT 2003
6945	K	31685	1954		BAT 2005
6989	T	14900	1996		
6990	T	20618	1974		Advent 1997
6991	T	3688	1978		BAT 2003
6992	K	20618	1974		Advent 1997
6993	T	3688	1978		BAT 2003
6995	T	3688	1978		BAT 2003
6997	K	7135	1978		BAT 2003
7004	T	700	1969	Steam Plant	BAT 2005
7005	T	4748	1954	Motor Pool	
7006	T	5215	1958	Motor Pool	
7007	T	120	1958		BAT 2004
7008	T	2828	1956	Steam Plant	BAT 2005
7009	T	192	1958	Motor Pool	
7010	T	124	1958	Motor Pool	
7012	T	151	1958	Steam Plant	BAT 2005
7013	T		1958	Pump house	BAT 2005
7014	T	2280	1958	Grease Rack	
7035	K	2700	1986		
7039	K	126841	2002		
7042	K	4808	1954	Motor Pool	
7043	K	4748	1958	Motor Pool	BAT 2004
7045	K	151	1958	Motor Pool	
7047	K	5077	1967	Motor Pool	BAT 2005
7048	K	20601	2002		
7049	K	5217	1954	Motor Pool	
7050	K	4808	1954	Motor Pool	
7051	K	124	1958	Motor Pool	
7052	K	3779	2002		
7053	K	151	1958	Motor Pool	
7055	K	151	1958	Motor Pool	
7057	K		1967	Grease Rack	
7060		1999	1986		
7060	K	3600	1989		
7060		1200	1989		
7060		1200	1989		
7061	K	728	1986		
7062	K	21279	1986		
7062		1600	1989		
7064	K		1986	Grease Rack	
7065	K	96	1996		
7066	K		1986	Grease Rack	
7068	K		1986	Grease Rack	
7070	K		1986	Grease Rack	
7072	K	120	1986		
7075	K	61419	2002		
7076	K	14284	2002		
7077	K	14284	2002		
7078	K	13347	2002		
7080	K	120	1986		
7081	K	14284	2002		
7083	K	120	1985		
7084	K	14284	2002		
7085	K	17418	1985		
7085	K	17418	1985		
7087	K	560	1985		
7088	K		1985	Grease Rack	
7089	K		1985	Grease Rack	
7090	K	120	1985		
7092	K	2800	1985		

Appendix D - OMA Lead-Based Paint Survey
Master Building List - 15 Sep 2005

Received a Lead Survey					
Needs a Lead Survey					
Low Priority for Survey					
7093	K	2800	1985		
7094	K	111448	1996		
7095	K	141116	1996		
7096	K	99706	1997		
7097	K	10398	1996		
7098	K	10399	1996		
7099	K	10399	1996		
7100	K	144	1996		
7106	K	10398	1997		
7107	K	10396	1997		
7108	K	1684	1993		
7110	K	23628	1969		BAT 2005
7111	K	21398	1996		
7112	K	25625	1969		BAT 2005
7113	K	14729	1996		
7114	K	7173	1969		BAT 2003
7116	K	6909	1959		BAT 2003
7117	K	3401	1997		
7118	K	25625	1959		BAT 2002
7119	K	9597	1997		
7120	K	25625	1959		BAT 2005
7121	K	3440	1994		
7123	K	22750	1996		
7124	K	27287	1997		
7125	K	10800	1996		
7126	K	10830	1996		
7127	K	12950	1997		
7128	K	6570	1998		
7129	K	8743	1993		
7130	K	10200	1986		
7131	K	15404	1978		BAT 2003
7132	K	6550	1985		
7133	K	10269	1978		BAT 2003
7134	K	8742	1993		
7137	K	3840	1965		BAT 2003
7138	K	4170	1997		
7140		414	1959		BAT 2003
7140	K	412	1987		BAT 2003
7141	K	5389	1967	Motor Pool	BAT 2004
7141		192	1967	Motor Pool	BAT 2004
7141		120	1967	Motor Pool	BAT 2004
7142	K	5200	1985		
7143	K	5250	1999		
7144	K	5200	1985		
7145	K	2581	1956		BAT 2003
7146	K	36675	2002		
7149	K	9248	1974		BAT 2003
7150	K	9237	1971		BAT 2003
7152	K	20511	1963	Hanger	BAT 2003
7153	K	1200	1963		
7154	K		1963	Hanger	BAT 2003
7154		1200	1980	Hanger	
7155	K	4518	1963		BAT 2002
7156	K	34785	1963	Hanger	BAT 2003
7157	K	6649	1971		BAT 2003
7158	K	100	1993		
7159	K	4259	1967		BAT 2003
7160	K	12516	1959		BAT 2002
7161	K	11218	1959	Hanger	BAT 2003
7163	K	11756	1975		BAT 2003
7163		156	1975		

Appendix D - OMA Lead-Based Paint Survey
Master Building List - 15 Sep 2005

Received a Lead Survey					
Needs a Lead Survey					
Low Priority for Survey					
7164	K	3105	1956		BAT 2003
7165	K	954	1981		
7167	K	1881	1959		BAT 2005
7168	K	1504	1953		
7169	K	1881	1959	Not a Bldg.	
7170	K	8400	1967		BAT 2003
7170		4000	1984		
7171	K	1018	1967		
7172	K	336	1965	Shack	BAT 2005
7173	K	4000	1965		BAT 2003
7175	K	1018	1967		
7176	K	3230	1983		
7177	K	5512	1965		BAT 2003
7178	K	120	1983		
7179	K	9300	1965		BAT 2003
7180	K	172	1994		
7181	K	4080	1969		
7187	K	1734	1959		BAT 2003
7188	K	5519	1993		
7189	K	5520	1993		
7191	K	13524	1996		
7201	K		1975	Receiver Bldg.	BAT 2005
7201		186	1975	Receiver Bldg.	BAT 2005
7202	K	1392	1959		BAT 2003
7203	K	441	1989		
7206	K	24178	1974		
7208	K	41912	1974		BAT 2003
7208		1000	1984		
7210	K	32611	1974		
7211	K	5200	1985		
7212	K	1849	1975		BAT 2003
7213	K	5231	1985		
7214	K	41860	1974		BAT 2003
7215	K	5200	1985		
7216	K		1985	Wash Rack	
7218	K	41860	1974		BAT 2004
7219	K		1974		BAT 2003
7221	K	536	1974		
7223	K	2530	1974		
7225	K	5200	1985		
7238	K	100	1999	Guard Shack	
7240	K	5200	1987		
7241	K	4556	1975		BAT 2003
7242	K	3000	1993		
7243	K	41117	1991		
7244	K	44578	1999		
7245	K	49139	1975		
7246	K	4200	1997		
7249	K	49369	1975		
7250	K	48	1997	Guard Shack	
7251	K	41117	1991		
7252	K	3943	1996		
7253	K	3943	1996		
7254	K	1054	2000		
7260	K	11370	1992	Wash Rack	
7261	K	4648	1999		
7262	K	69243	1992		
7263	K	4674	1994		
7264	K	60000	1990		
7265	K	4232	1997		
7266	K	970	1990	Wash Rack	

Appendix D - OMA Lead-Based Paint Survey
Master Building List - 15 Sep 2005

Received a Lead Survey					
Needs a Lead Survey					
Low Priority for Survey					
7267	K	19441	1993		
7268	K	60400	1990		
7270	K	1711	1988	Wash Rack	
7272	K	38968	1988		
7272	K		1988		
7273	K	4987	1993		
7274	K	85410	2001		
7275	K	5200	1994		
7276	K	12486	1995		
7277		187	1994		
7277	K	22033	1994		
7278	K	12487	1995		
7279	K	5057	1994		
7280	K	4507	1993		
7281	K	11270	1992		
7282	K	4523	1995		
7283	K	4524	1995		
7284	K	1495	2000		
7285	K	5684	1993		
7286	K	5683	1996		
7287	K	5684	1996		
7288	K	5684	1996		
7289	K	5683	1993		
7290		8400	1997		
7290	K		1996		
7293	K	368	1959		BAT 2005
7294	K	72	1993		
7297	K	159	1959		BAT 2005
7297		157	1959		BAT 2005
7298	K	3985	1997	Wash Rack	
7299	K	3939	1996		
7347	T	1198	1969		
7352	T	1864	1942		
7502	T	1227	1951		BAT 2003
7503	T	688	1951		BAT 2005
7504	T	5996	1951		BAT 2003
7509	T	775	1995		
7510	T	14280	1957		BAT 2003
7514	T	4064	1957		BAT 2003
7520	T	5904	1957		BAT 2004
7523	T	62638	1950		Advent 1995
7524	T	800	1994		
7526	T	5655	1950		BAT 2005
7527	T	5980	1950		BAT 2004
7540	T	11574	1955		BAT 2003
7541	T	8908	1953		BAT 2004
7542	T	1170	1955		BAT 2005
7543	T	998	1960		BAT 2003
7546	T	980	1965		BAT 2005
7562	T	1800	1954		BAT 2004
7563	T	1026	1953		BAT 2004
7565	T	1008	1960		BAT 2005
7572	T	6900	1950		BAT 2003
7573	T	4060	1950		BAT 2005
7574	T	325	1950		BAT 2005
7575			1997		
7580	T	12550	1956		BAT 2005
7603	T	2980	1950	Demo List '97	
7604	T	5620	1950		Advent 1996
7605	T	80	1950		BAT 2005
7606	T	718	1951		Advent 1995

Appendix D - OMA Lead-Based Paint Survey
Master Building List - 15 Sep 2005

Received a Lead Survey					
Needs a Lead Survey					
Low Priority for Survey					
7607	T	1200	1950		Advent 1997
7608	T	592	1951		BAT 2005
7609	T	1440	1950		
7611	T	3360	1951		
7620	T	4430	1952		BAT 2003
7621	T	4430	1952		BAT 2003
7626	T	800	1953		
7630	T	288	1954		
7635	T	400	1982		
7635		400	1982		
7635	T		1943	Pump house	BAT 2003
7700	T	4086	1950	Bunker	
7702	T	3411	1950	Bunker	BAT 2004
7703	T		1952		BAT 2005
7704	T	3358	1950	Bunker	
7706	T	4180	1950	Bunker	
7708	T	4958	1950	Bunker	
7710	T	3099	1950	Bunker	
7712	T	2798	1950	Bunker	
7714	T	3657	1950	Bunker	
7716	T	3543	1950	Bunker	
7718	T	3657	1950	Bunker	BAT 2004
7720	T	4383	1950	Bunker	BAT 2004
7722	T	3874	1950	Bunker	
7724	T	921	1954	Bunker	
7726	T	3465	1950	Bunker	
7728	T	4912	1950	Bunker	
7732	T	4549	1950	Bunker	
7734	T	3248	1950	Bunker	
7735	T	1024	1976	Bunker	BAT 2005
7736	T	3590	1950	Bunker	
7738	T	3590	1950	Bunker	
7740	T	10655	1950	Bunker	
7742	T	2796	1950	Bunker	
7744	T	3749	1950	Bunker	
7746	T	3350	1950	Bunker	
7748	T	3174	1950	Bunker	
7750	T	3599	1950	Bunker	
7752	T	2970	1950	Bunker	
7811	T	22835	1961		BAT 2003
7812	T	1920	1957		BAT 2005
7813	T	100	1966	Not a Bldg.	
7814	T	2108	1953		BAT 2004
7819		7750	1997	Car Port	
7820	T	3224	1953		BAT 2004
7821	T	540	1981		BAT 2004
7824	T	144	1999		
7825	T	15111	1961		BAT 2003
7830	T	2353	1952		BAT 2003
7831	T	36	1952		BAT 2003
7832	T	1930	1953		BAT 2005
7833	T	8804	1953		BAT 2003
7834	T	13459	1949		BAT 2003
7835	T	2108	1952		BAT 2003
7843	T	1440	1950		
7845	T	274	1949		
7847	T	336	1949		
7851	T	1089	1951		BAT 2004
7854	T	7700	1986		
7855	T	10815	1951		BAT 2003
7856	T	9607	1952		BAT 2004

Appendix D - OMA Lead-Based Paint Survey
Master Building List - 15 Sep 2005

Received a Lead Survey					
Needs a Lead Survey					
Low Priority for Survey					
7857	T	9618	1967		
7858	T	4284	1957		BAT 2003
7860	T	2171	1954		BAT 2003
7861	T	2171	1954		
7862	T	2171	1954		BAT 2003
7863	T	2171	1954		
7865	T	2171	1954		BAT 2003
7871	T	1698	1952		BAT 2003
7872	T	787	1957		BAT 2003
7873	T	1746	1949		
7874	T	3012	1952		BAT 2003
7877	T	2472	1954		
7882	T	7174	1949		BAT 2004
7884	T	290	1966		
7900	T	2392	1951	Bunker	
7901	T	2391	1951	Bunker	
7902	T	2391	1951	Bunker	
7903	T	2391	1951	Bunker	
7904	T	2391	1951	Bunker	
7905	T	2391	1951	Bunker	
7906	T	2391	1951	Bunker	
7907	T	2391	1951	Bunker	
7908	T	2387	1951	Bunker	
7909	T	2387	1951	Bunker	
7910	T	2387	1951	Bunker	
7911	T	1865	1951	Bunker	
7912	T	2393	1951	Bunker	
7913	T	2387	1951	Bunker	
7914	T	2391	1951	Bunker	
7915	T	2391	1951	Bunker	
7916	T	2391	1951	Bunker	
7917	T	2397	1951	Bunker	
7918	T	2395	1951	No Access	
7919	T	2392	1951	No Access	
7920	T	2395	1951	Bunker	
7921	T	2387	1951	Bunker	
7922	T	2399	1951	Bunker	
7923	T	2447	1951	Bunker	
7924	T	2447	1951	Bunker	
7925	T	2447	1951	Bunker	
7926	T	2392	1951	Bunker	
7927	T	2392	1952	Bunker	
7928	T	2147	1952	Bunker	
7929	T	2147	1952	Bunker	
7930	T	2147	1952	Bunker	
8000	T	2147	1952	Bunker	BAT 2004
8001	T	2147	1952	Bunker	
8002	T	2147	1952	Bunker	BAT 2004
8003	T	2147	1952	Bunker	BAT 2004
8004	T	2147	1952	Bunker	BAT 2005
8005	T	2147	1952	Bunker	BAT 2005
8006	T	2419	1952	Bunker	BAT 2005
8007	T	2419	1952	Bunker	
8008	T	2419	1952	Bunker	BAT 2005
8009	T	2419	1952	Bunker	
8010	T	2419	1952	Bunker	
8011	T	2419	1952	Bunker	
8012	T	2419	1952	Bunker	BAT 2005
8013	T	2419	1952	Bunker	BAT 2005
8014	T	2419	1952	Bunker	BAT 2005
8015	T	2419	1952	Bunker	BAT 2005

Appendix D - OMA Lead-Based Paint Survey

Master Building List - 15 Sep 2005

Received a Lead Survey					
Needs a Lead Survey					
Low Priority for Survey					
8016	T	2419	1952	Bunker	BAT 2005
8017	T	2419	1952	Bunker	BAT 2005
8018	T	2419	1952	Bunker	BAT 2005
8019	T	2419	1952	Bunker	BAT 2005
8020	T	2419	1952	Bunker	BAT 2005
8021	T	2419	1952	Bunker	BAT 2005
8022	T	2419	1952	Bunker	BAT 2005
8023	T	2419	1952	Bunker	BAT 2005
8024	T	2419	1952	Bunker	BAT 2005
8025	T	2419	1952	Bunker	BAT 2005
8026	T	2419	1952	Bunker	BAT 2005
8027	T	2419	1952	Bunker	BAT 2005
8028	T	2419	1952	Bunker	BAT 2005
8029	T	2419	1952	Bunker	BAT 2005
8030	T	2419	1952	Bunker	BAT 2005
8031	T	2419	1952	Bunker	BAT 2005
8032	T	2419	1952	Bunker	BAT 2005
8033	T	2419	1952	Bunker	BAT 2005
8034	T	2419	1952	Bunker	BAT 2005
8035	T	2519	1952	Bunker	BAT 2005
8036	T	2519	1952	Bunker	BAT 2005
8037	T	2519	1952	Bunker	BAT 2005
8038	T	2519	1952	Bunker	BAT 2005
8039	T	2519	1952	Bunker	BAT 2005
8040	T	2419	1952	Bunker	BAT 2005
8041	T	2419	1952	Bunker	BAT 2005
8042	T	2419	1952	Bunker	
8043	T	2419	1952	Bunker	BAT 2005
8044	T	2419	1952	Bunker	
8045	T	2419	1952	Bunker	BAT 2005
8046	T	2419	1952	Bunker	
8047	T	2419	1952	Bunker	BAT 2005
8048	T	2419	1952	Bunker	BAT 2005
8049	T	2419	1952	Bunker	BAT 2005
8050	T	2419	1952	Bunker	BAT 2005
8051	T	2419	1952	Bunker	BAT 2005
8052	T	2419	1952	Bunker	
8053	T	2419	1952	Bunker	BAT 2005
8054	T	2419	1952	Bunker	BAT 2005
8055	T	2419	1952	Bunker	BAT 2005
8056	T	2419	1952	Bunker	BAT 2005
8057	T	2419	1952	Bunker	BAT 2005
8058	T	2419	1952	Bunker	BAT 2005
8059	T	2419	1952	Bunker	BAT 2005
8060	T	2419	1954	Bunker	BAT 2005
8062	T	4432	1975		
8063	T	4432	1975		
8064	T	4432	1975		
9001	T	3250	1999		
9002	T	4732	1999		
9010	T	6598	2002		
9011	T	474	2002		
Bldg. 1	T			Craig Village	BAT 2003
Bldg. 2	T			Craig Village	BAT 2003
Bldg. 3	T			Craig Village	BAT 2003
Bldg. 4	T			Craig Village	BAT 2003
Bldg. 5	T			Craig Village	BAT 2003
Bldg. 6	T			Craig Village	BAT 2003
Bldg. 7	T			Craig Village	BAT 2003
Bldg. 8	T			Craig Village	BAT 2003
Bldg. 9	T			Craig Village	BAT 2003

Appendix D - OMA Lead-Based Paint Survey Master Building List - 15 Sep 2005

Received a Lead Survey
Needs a Lead Survey
Low Priority for Survey

566	- Surveys Conducted by BAT
22	- Surveys Conducted by Other Contractors
588	- Total Surveys Conducted
228	- Needs to be Surveyed
402	- Low Priority for Survey
1218	- Total Number of Buildings